

ATTO FibreBridge 1290/2300/2350 Interoperability Matrix

	1290E	2300E/R/D	2350C	
Operating System	Apple Tiger OS 10.4.X	X	X	X
	Apple Panther OS 10.3.X	X	X	X
	Linux: RedHat	X	X	X
	Sun Solaris 10	X	X	X
	Windows XP, Server 2003, 2000	X	X	X
Fibre Channel HBA's	ATTO FC3300	X	X	X
	ATTO Celerity 21PS	X	X	X
	ATTO Celerity 22XH	X	X	X
	ATTO Celerity 24XL	X	X	X
	ATTO Celerity 41XS	X	X	X
	ATTO Celerity 42ES	X	X	X
	ATTO Celerity 42XS	X	X	X
	ATTO Celerity 44ES	X	X	X
	Emulex LP9002	X	X	X
	Emulex LP9802	X	X	X
	Emulex LP10000	X	X	X
	LSI 7102XP	X	X	X
	LSI 7202XP	X	X	X
	LSI 7402XP	X	X	X
	QLogic 2310F	X	X	X
	QLogic 2340	X	X	X
QLogic 2342	X	X	X	
QLogic 2344	X	X	X	
Fibre Channel Switches	Brocade Silkworm 3250	X	X	X
	Brocade Silkworm 3850	X	X	X
	MDS9216	X	X	X
	QLogic SANbox 3050	X	X	X
	QLogic SANbox 5200	X	X	X
Removable Tape / MO Storage	ADIC Scalar 24	X	X	X
	ADIC Scalar 100	X	X	X
	Exabyte VXA-2 Packetloader	X	X	X
	HP LTO1	X	X	X
	HP LTO2	X	X	X
	IBM LTO1	X	X	X
	IBM LTO2	X	X	X
	IBM LTO3	X	X	X
	Overland NEO 2000	X	X	X
	Quantum M1500	X	X	X
	Quantum M2500	X	X	X
	Quantum Superloader	X	X	X
	Quantum DLT 8000	X	X	X
	Quantum SDLT 320	X	X	X
	Quantum SDLT 600	X	X	X
	Sony AIT-3	X	X	X
	Sony AIT-4	X	X	X
	Sony SAIT-1	X	X	X
Sony CSM-20	X	X	X	
Sony LIB-81	X	X	X	
Sony LIB-162	X	X	X	
Disk Storage Devices	ATTO Diamond w/SCSI option	X	X	X
	JMR	X	X	X
Independent Software Applications	BakBone Netvault	X	X	X
	CA ArcServe	X	X	X
	Commvault Galaxy	X	X	X
	EMC/Dantz Retrospect	X	X	X
	Legato Networker	X	X	X
	Sanbolic LaScala/MelioFS	X	X	X
	Veritas BackupExec	X	X	X
	Veritas NetBackup	X	X	X
	Windows 2003 Native Backup	X	X	X

Disclaimer: The ATTO Interoperability Matrix is a general guideline that is not specific to firmware, version, revision, specification level or test configuration of ATTO or third-party products. ATTO Technology tests products on an ongoing basis and new equipment is constantly being added. The Interoperability Matrix may not reflect the most current information. If a specific product is not shown, please contact ATTO Technical Services at 800-858-9598 for additional information. Inclusion of any product on this list does not guarantee compatibility. Customer-specific configurations may influence compatibility. Please check the ATTO Technology website at www.attotech.com for additional details.