



## Celerity Fibre Channel Release v2.66 - Linux

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the Celerity Fibre Channel adapter product v2.66 that was released on 12/30/2010. This information pertains to the Linux OS.

### 2. Changes

---

- **Version 2.66 (Released 12/3/2008)**
  - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
  - The following apply to changes made from v2.64 to v2.66
    - Added support for Red Hat Enterprise Linux 6
    - Improved interoperability with latest versions of Linux distribution
- **Version 2.64 (Released 12/3/2008)**
  - **Note:** It is recommended that firmware dated 091119 be utilized with this driver release.
  - The following apply to changes made from v2.63 to v2.64
  - **Incident Resolutions/Bug Fixes/Changes**
    - Improved initiator task management
    - Miscellaneous compilation fixes
    - Fixed a bug in Linux-Rescan-Host-Routine that could lead to invalid outstanding references to the driver. This would prevent the driver from being unloaded
    - OEM Specific 42RO
- **Version 2.62 (Released 6/9/2008)**
  - **Note:** It is recommended that firmware dated 11/13/07 be utilized with this driver release.
  - The following apply to changes made from v2.61 to v2.62
  - **Incident Resolutions/Bug Fixes/Changes**
    - Support added for Linux Kernel 2.6.25
    - Addressed hardware check while loading Linux
    - Fixed an issue that would only show 6 of 8 ports if two (2) 44ES Celerity host adapters were installed in the same machine.
- **Version 2.61 (Released 2/29/2008)**
  - **Note:** It is recommended that firmware dated 11/13/07 be utilized with this driver release.
  - The following apply to changes made from v2.60 to v2.61
  - **New Features**
    - Full driver support for the 41EL Host adapter

### 3. Known Issues/Advisements

- 
- None

#### 4. Affected Products

---

Product Name	SKU
Celerity FC 44ES	CTFC-44ES-000
Celerity FC 42ES	CTFC-42ES-000
Celerity FC 41ES	CTFC-41ES-000
Celerity FC 41EL	CTFC-41EL-000
Celerity FC 42XS	CTFC-42XS-000
Celerity FC 41XS	CTFC-41XS-000

#### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)