



Celerity Fibre Channel Release v1.00 - VMware

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the Celerity Fibre Channel adapter product v1.00 that was released on 3/19/2010. This information pertains to the VMware ESX Server v3.5 OS update 5.

2. Changes

- **Version 1.00 (Released 3/19/2010)**
 - **Note:** It is recommended that firmware dated 091119 be utilized with this driver release.
 - Maintenance release of VMware ESX 3.5 u5 driver *for the Celerity 4Gb FC adapters*.
 - **New Features, Enhancements and Changes**
 - VMware re-build of drivers for ESX 3.5 U5 release.

3. Known Issues/Advisements

- None

4. Affected Products

Product Name	SKU
Celerity FC 44ES	CTFC-44ES-000
Celerity FC 42ES	CTFC-42ES-000
Celerity FC 41ES	CTFC-41ES-000

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com