



## Celerity Fibre Channel Release v1.33 - VMware

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the Celerity Fibre Channel adapter product v1.33 that was released on 10/28/2011. This information pertains to the VMware ESX Server v4.x OS.

### 2. Changes

---

- **Version 1.33 (Released 10/31/2011)**
  - **Note:** It is recommended that firmware dated 100728 be utilized with this driver release.
  - *Initial release of VMware ESX 4.x driver for the Celerity 8Gb FC adapters.*
  - **New Features, Enhancements and Changes**
    - Added support for NPIV
    - Improved functionality in NPIV vMotion
    - Improved handling of Windows 2k3 r2 x64 (or better) installation in a VM
  
- **Version 1.23 (Released 8/25/2010)**
  - **Note:** It is recommended that firmware dated 100728 be utilized with this driver release.
  - *Initial release of VMware ESX 4.x driver for the Celerity 8Gb FC adapters.*
  - **New Features, Enhancements and Changes**
    - Documented support for VMware ESX Server v4.x

### 3. Known Issues/Advisements

---

- 

### 4. Affected Products

---

Product Name	SKU
Celerity FC 84EN	CTFC-84EN-000
Celerity FC 82EN	CTFC-82EN-000
Celerity FC 81EN	CTFC-81EN-000

## 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)