



Celerity Fibre Channel BIOS Config Release v091113

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the Celerity Fibre Channel Host Adapter flash bundle package, version 091113, which was released on 11/19/09. This information pertains to the flash bundles and BIOS utility associated with the Celerity Fibre Channel Host Bus Adapter product.

2. Changes

- **Version 3.23 (Released 11/19/2009)**
 - **Note:** The following apply to v3.23.
 - **New Features, Enhancements and Changes**
 - [BIOS, Config] Feature enhancements related to Point-to-Point direct connect mode in the BIOS driver.

- **Version 3.22 (Released 8/31/2009)**
 - **Note:** The following apply to v3.22.
 - **New Features, Enhancements and Changes**
 - [BIOS, Config] Adapter discovery loop repeats until adapter count reaches the maximum, resulting in adapter duplicates showing in the discovery list on the Dell T 610.

3. Known Issues/Advisements

- None

4. Affected Products

Product Name	SKU
Celerity FC 81EN	CTFC-81EN-000
Celerity FC 82EN	CTFC-82EN-000
Celerity FC 84EN	CTFC-84EN-000
Celerity FC 41XS	CTFC-41XS-000
Celerity FC 42XS	CTFC-42XS -000
Celerity FC 41ES	CTFC-41ES-000
Celerity FC 42ES	CTFC-42ES-000
Celerity FC 44ES	CTFC-44ES-000

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com