



ATTO Technology, Inc.

# Product Release Notes

## ExpressSAS H6F0 GT HBA Release v1.05 - Mac® OS X

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ExpressSAS H6F0 GT host adapter product v1.05 that was released on January 31, 2012. This information pertains to Mac OS X 10.5, or later, for Intel® based systems.

### 2. Changes

- **Version 1.05 (Released 01/31/2012)**
  - **Note:** It is recommended that firmware dated 01/31/2012 be utilized with this driver release.
  - **New Features, Enhancements and Changes**
    - Initial production release for the H6F0 GT.

### 3. Known Issues/Advisements

- The driver is not fully SAT compliant (SCSI-to-ATA Translation for SATA support). The following SCSI commands are not translated: FORMAT UNIT, REASSIGN BLOCKS, SECURITY PROTOCOL IN, and SECURITY PROTOCOL OUT. There is no known user impact.

### 4. Affected Products

Product Name	SKU
ExpressSAS H6F0 GT Adapter	ESAS-H6F0-GT0

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)