



ATTO Technology, Inc.

Product Release Notes

FastFrame™ 40GbE NIC v1.00 – RHEL 7.1, SUSE Server 12

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the FastFrame 40GbE v1.00 Linux release, specifically RHEL 7.1 and SUSE Linux Enterprise Server 12.

2. Changes

- **Version 1.00 (Released 09/17/2015)**
 - **New Features, Enhancements and Changes**
 - Initial release for the FastFrame 40GbE NIC drivers for Linux

3. Known Issues/Advisements

- Flash utility support upcoming
- Kernel panic may occur if SLES12 is configured to act as an NFS-over-RDMA server

4. Affected Products

| Product Name | SKU |
|----------------------|--|
| FastFrame 40GbE NICs | FFRM-NQ41-000 FFRM-NQ42-000 FFRM-NQ41-DA0 FFRM-NQ42-DA0 |

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit attotech.com/support for technical support hours.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com