



ATTO Technology, Inc.

Product Release Notes

ThunderLink Fibre Channel 2162/2082 Multipath Director Release V1.61MP – Windows

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink Fibre Channel 2162/2082 adapter product v1.65MP that was released on 03/19/2015. This information pertains to Windows 7, 8 and 8.1. **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.

2. Changes

- **Version 1.65MP** (03/19/2015)
 - **New Features/Enhancements**
 - Initial release of Mac drivers for the ThunderLink FC 2162 and 2082.
 - **Supported OS**
 - Windows 7, 8 and 8.1.

3. Known Issues/Advisements

- None

4. Affected Products

Product Name	SKU
ThunderLink FC 2162 Desklink device	TLFC-2162-D00
ThunderLink FC 2082 Desklink device	TLFC-2082-D00

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com