



## ThunderLink™ FC 2082 and 2162 Release v1.00 – Microsoft Certified

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 2082 and 2162 Desklink Devices, version 1.00, which was released on 09/02/14. This information pertains to Microsoft Windows Operating System including Windows 7, 8 and 8.1 platforms.

### 2. Changes

- **Version 1.00 (Released 09/02/14)**
  - **New Features, Enhancements and Changes**
    - Initial release for the ThunderLink FC 2082 and 2162 Desklink Device.
    - Microsoft WHQL certification performed on drivers for Windows 7 (x64 and x86) and Windows 8 (x64 and x86)

### 3. Known Issues/Advisements

- No known advisements.

### 4. Affected Products

Product Name	SKU
ThunderLink FC 2082	TLFC-2082-D00/DE0
ThunderLink FC 2162	TLFC-2162-D00/DE0

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO’s goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)