



## ThunderLink™ NS 1101 Release v1.00 - Mac OS® X

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink NS 1101 Thunderbolt to Ethernet (10Gb optical SFP+) Desklink™ device, version 1.00, which was released on 08/17/12. This information pertains to the Mac OS X platform for Intel® based systems.

### 2. Changes

- **Version 1.00 (Released 08/17/12)**
  - **New Features, Enhancements and Changes**
    - Initial release for the ThunderLink NS 1101 desklink.

### 3. Known Issues/Advisements

- No known advisements.

### 4. Affected Products

Product Name	SKU
ThunderLink NS 1101 Desklink Device	TLNS-1101-D00

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)