



ATTO Technology, Inc.

# Product Release Notes

## ThunderStream SC 3808D Flash Bundle v120809

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ThunderStream SC 3808D RAID Storage Controller desklink flash bundle package, version 120809, which was released on 08/09/12. This information pertains to the flash bundles and BIOS utility associated with the ThunderStream SC 3808D desklink device.

### 2. Changes

---

- **Version v120809 (Released 08/09/12)**
  - **New Features, Enhancements and Changes**
    - Initial release for the ThunderStream 3808D desklink.

### 3. Known Issues/Advisements

---

- No known advisements.

### 4. Affected Products

---

Product Name	SKU
ThunderStream SC 3808D Desklink Device	TSSC-3808-D00

### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)